# Department of Historic Resources
## Reconnaissance Level Survey

**Isle Of Wight** *DHR Id#:* **046-0105**

### *Resource Identification*

*Property Name(s):* ..... House, Route 610 {Function/Location}
*Property Date:* ..... 1870
*Address(s):* ..... Route 610 {Current}
*County/Independent City:* Isle Of Wight
Vicinity of: ..... Windsor
*State, Zip:* .....Virginia
*USGS Quad Name:* ..... WINDSOR

***National Register Eligibility Status***
Property is Historic (50 years or older)

Property has not been evaluated

### *Resource Description*

*Primary Resource Exterior Componant Description:*

| Component | Comp Type/Form | Material | Material Treatment |
|---|---|---|---|
| Chimneys | Chimneys - Interior end | Brick | |
| Chimneys | Chimneys - Exterior end | Brick | |
| Porch | Porch - 1-story, 3-bay | Wood | Porch - Posts, Turned |
| Roof | Roof - Gable | Asphalt | Roof - Shingle |
| Structural System | Structural System - Frame | Wood | Structural System - Weatherboard |
| Windows | Windows - Sash, double-hung | Wood | Windows - 2/2 |

*WUZIT Count:*

| No. | Wuzit Types | Historic? |
|---|---|---|
| 1 | Single Dwelling | Historic |

*NR Resource Count:*

### *Individual Resource Information*

*WUZIT:* ..... Single Dwelling

*Est. Date of Construction:* .... 1870 ca {VDHR Survey File}
*Primary Resource?* ..... Yes
*Architectural Style:* ..... Other
*Interior Plan Type:* ..... Central Passage, Single Pile
*Accessed?* .....
*Number of Stories:* ..... 2.0
*Condition:* .....
*Threats to Resource:* .....

*Description:* Architecture Summary: End Architecture Summary Additions and alterations: End Additions and alterations Interior Description: I-house
End Interior Description

### *Cemetery Information*

### *Bridge Information*

### *National Register Eligibility Information (Intensive Level Survey)*

*Historic Context(s):* ..... Domestic

*Significance Statement:* Late 19th century I-house with one exterior brick chimney and l one interior brick stove chimney.

### *Bibliographic Documentation*

### *Ownership Information*

Report generated 11/17/04

### *Graphic Media Documentation*

| *Medium* | *Depository ID #* | *Photo Depository* | *Date* | *File Name* |
|---|---|---|---|---|
| B&W 35mm Photos | | | 0 /99/99 | |

### *Cultural Resource Management (CRM) Events*

*CRM Event* # 1,
*Cultural Resource Management Event:* ..... Reconnaissance Survey
*Date:* ..... ..... 1990/7 /4
*Organization or Person:* ..... Willie Graham
*CRM Event Notes or Comments:* .....

# VIRGINIA
# DIVISION OF HISTORIC LANDMARKS
## HISTORIC DISTRICT/BRIEF SURVEY FORM

File no. 46-105
Negative no(s).

City/Town/Village/Hamlet: Windsor Vicinity
County: Isle of Wight
Street address or route number: Rte. 610, 1 mi. north of Rte. 609
U.S.G.S. Quad: Windsor
Historic name:
Common name:

Present use: Dwelling
Original use: Dwelling
Building Style: Vernacular
Building Date(s): late 19th century

1. Construction Materials

- [x] wood frame
- [ ] brick
  - bond: [ ] English [ ] Flemish [ ] ____-course American [ ] stretcher [ ] other ____
- [ ] stone
  - [ ] random rubble
  - [ ] coursed rubble
  - [ ] ashlar [ ] dressed [ ] rock-faced
- [ ] log:
  - [ ] squared [ ] unsquared
  - notching: [ ] V-notch [ ] saddle [ ] square [ ] half dovetail [ ] full dovetail [ ] diamond
- [ ] concrete block
- [ ] terra cotta
- [ ] steel frame
- [ ] other ____

2. Cladding Material

- [x] weatherboard
- [ ] vertical siding
- [ ] board & batten
- [ ] shingle: [ ] wood [ ] asbestos [ ] asphalt
- [ ] bricktex
- [ ] other ____
- [ ] composition siding
- [ ] stucco
- [ ] aluminum or vinyl siding
- [ ] cast iron
- [ ] sheet metal
- [ ] enameled metal
- [ ] glass



3. Stories (number): 2
- [ ] low basement
- [ ] raised basement

4. Bays (number): front 3 side (church) ____
- [x] symmetrical
- [ ] asymmetrical

5. Roof Type
- [ ] shed [ ] parapet?
- [x] gable [ ] pediment? [ ] parapet? [ ] clipped end? [ ] cross gable? [ ] central front gable?
- [ ] other ____
- [ ] hipped [ ] pyramidal?
- [ ] mansard
- [ ] false mansard
- [ ] gambrel
- [ ] flat [ ] parapet?
- [ ] roof not visible

6. Roofing Material
- [x] shingle
  - [x] composition (asphalt, asbestos, etc.)
  - [ ] wood
- [ ] metal
  - [ ] standing seam
  - [ ] corrugated
  - [ ] pressed tin (simulated shingles)
- [ ] tile
  - [ ] pantile [ ] flat [ ] glazed
- [ ] slate
- [ ] not visible

7. Dormers (number): front ____ side ____
- [ ] gable [ ] pediment?
- [ ] shed
- [ ] hipped

8. Primary Porch
- style ____
- stories 1
- levels 1 bays 3
- materials wood, asphalt shingles
- description and decorative details: Turned columns, hipped roof.

9. General supplementary description and decoration: Exterior brick chimney one end, interior brick stove chimney other end. Two-over-two sash. Unbeaded weatherboards.

10. Major additions and alterations:

11. Outbuildings:

12. Landscape Features:

13. Significance: Late 19th-century I house with one exterior brick chimney and one interior brick stove chimney.

Surveyed by: Willie Graham Date: 7/4/90




FIGURE 9
Architectural Resources Identified During Survey